IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventors: L. Olsson et al. Attorney Docket No.: FRAB125183

Patent No.: 7374035 Application No.: 10/535721

Issued: May 20, 2008 Filing Date: January 6, 2006

Confirmation No.: 9229

Title: SUPPORTING INSTALLATION AND BEARING ELEMENT THEREFOR

REQUEST FOR CERTIFICATE OF CORRECTION

Seattle, Washington 98101

ATTN: CERTIFICATE OF CORRECTION BRANCH

COMMISSIONER FOR PATENTS:

Enclosed is a Certificate of Correction, Form PTO 1050, for the above-identified U.S. Letters Patent. The errors in the printed patent listed on the enclosed form occurred at the corresponding locations in the application file listed below:

Column,	Line	Page,	Line
(30) Pg. 1, Col. 1	Foreign Appln. Priority Data	USPTO Filing Receipt of 3/13/06	Foreign Applns.
10 (Claim 9,	47 line 2)	3 (Claim 38,	12 line 2)
11 (Claim 18,	12 line 2)	(Amendment 4 (Claim 48,	19
(Claim 18,	line 2)	(Amendment	
12 (Claim 29,	34 line 3)	6 (Claim 59, (Amendment	

The Commissioner is hereby authorized to charge the fee of \$100 and any other fees associated with this paper, or credit any overpayment, to Deposit Account No. 03-1740.

Respectfully submitted,

CHRISTENSEN O'CONNOR JOHNSON KINDNESSPLLC

Matthew D. Balint Registration No. 61,038 Direct Dial No. 206.695.1651

Water Beld

MDB:dmg

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. : US 7374035 B2 DATED : May 20, 2008 INVENTORS : L. Olsson et al.

> It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN	LINE	ERROR
(30) Pg. 1, Col. 1	Foreign Appln. Priority Data	"0203419" should read0203419.7
10 (Claim 9,	47 line 2)	"spaced from" should readspaced apart from
11 (Claim 18,	12 line 2)	"by drive" should readby a drive
12 (Claim 29,	34 line 3)	"longitudinally" should readlongitudinal

PATENT NO. US 7374035 B2

No. of add'l copies @ 50¢ per page FRAB\25183173A DOC

MAILING ADDRESS OF SENDER: